

All 2008~2011 YW50 (ZUMA) MODELS
FACTORY MODIFICATION CAMPAIGN - Carburetor and Air Induction Box (Exhaust Emissions)
Yamaha Technical Bulletin M2011-006R.

Yamaha Motor Corporation, U.S.A. has decided that a defect (nonconformity) which relates to exhaust emission regulations exists in all 2008~2011 model YW50X/ Y/ Z/ A ("Zuma") scooters. A bulletin was originally issued on September 23, 2011.

Affected Models:

2008 YW50X:

SA20A-0810101~0819564

2009 YW50Y:

SA20A-0820101~0827260

2010 YW50Z:

SA20A-0870101~0870458

2011 YW50A:

SA20A-0910101~0910748

The reason for this recall: Because of the carburetor and air induction box system (AIS) box design on affected scooters, the carbon monoxide (CO) exhaust emissions levels do not conform to EPA (Environmental Protection Agency) emission regulations. These regulations were established to protect the public health or welfare from the dangers of air pollution.

What Yamaha and your dealer will do: To correct this nonconformity, your authorized Yamaha dealer will install a new carburetor and air induction box that do achieve CO exhaust emission levels within specifications. This is not a safety-related recall. Installing the new carburetor and AIS takes a little more than 45 minutes to do. Your dealer may need to keep your scooter longer depending upon their schedule. There will be no charge to you for this procedure.

What you should do now: Please call your Yamaha dealer to make a service appointment to have this procedure performed. At that same time, you can find out how long they expect to keep your scooter for this service. For the name of a dealer new you, call 1-800-88-YAMAHA or visit the "Find a Dealer" section of this website.